			8	9	10	11	12	14	15	16	17
	1pp	Glue HV bars									
		QC on panels									
		QC on HV bar gluing									
		Cleaning HV, top, gas bars									
		Cleaning, packing panels									

			8	9	10	11	12	13	14	15	16
day 1	***Ch 1***	Wire winding 2 gaps									
		Glue wires									
		Separate frames									
day 2	***Ch 1***	Test wire pos. / Solder. 2 gaps									
		Cut wires 2 gaps									
		Solder HV connect. 2 gaps									
		Wire tension measur 2 gaps									
		HV test gap 1&2									
		Wire winding 2 gaps									
		Glue wires									
		Separate frames									
day 3	***Ch 1***	Glue gas/top bars gaps 1&2									
		Test wire pos. / Solder. 2 gaps									
		Cut wires 2 gaps									
		Solder HV connect. 2 gaps									
		Wire tension measur 2 gaps									
		HV test gap 3&4									
	Ch 2	Wire winding 2 gaps									
		Glue wires									
		Separate frames									
day 4	***Ch 1***	Glue gas/top bars gaps 3&4									
	Ch 2	Test wire pos. / Solder. 2 gaps									
		Cut wires 2 gaps									
		Solder HV connect. 2 gaps									
		Wire tension measur 2 gaps									
		HV test gap 1&2									
		Wire winding 2 gaps									
		Glue wires									
		Separate frames									
day 5	***Ch1***	Glue 4 gaps									
	Ch 2	Glue gas/top bars gaps 1&2									
		Test wire pos. / Solder. 2 gaps									
		Cut wires 2 gaps									
		Solder HV connect. 2 gaps									
		Wire tension measur 2 gaps									
		HV test gap 3&4									
	Ch 3	Wire winding 2 gaps									
		Glue wires									
		Separate frames									
day 6	***Ch 2***	Glue gas/top bars gaps 3&4									
	Ch 3	Test wire pos. / Solder. 2 gaps									
		Cut wires 2 gaps									
		Solder HV connect. 2 gaps									
		Wire tension measur 2 gaps									
		HV test gap 1&2									
		Wire winding 2 gaps									
		Glue wires									
		Separate frames									
day 7	***Ch2***	Glue 4 gaps									
	Ch 3	Glue gas/top bars gaps 1&2									
		Test wire pos. / Solder. 2 gaps									
		Cut wires 2 gaps									
		Solder HV connect. 2 gaps									
		Wire tension measur 2 gaps									
		HV test gap 3&4									
		Wire winding 2 gaps									
		Glue wires									
		Separate frames									
day 8	***Ch 3***	Glue gas/top bars gaps 3&4									
day 9	***Ch 3***	Glue 4 gaps									